

3348 Route 208, Campbell Hall, NY 10916 Phone: 845-496-1600 Fax: 845-496-1398

12960 Commerce Lake Drive, A14, Fort Myers, FL 33913 42 Day Farm Road, West Stockbridge, MA 01266 1813 State Route 7, Harpursville, NY 13787 877 US-4, Schuylerville, NY 12871

| Client: | Aden Aggregates | Project: | Grasso Quarry QC 2025 |
|---------------|--------------------|-----------------|-----------------------|
| Item: | Bankrun Shale | Project Number: | 250005 |
| Source: | Aden-Grasso Quarry | Lab Number: | 25-0182 |
| Date Sampled: | 2/24/2025 | Sampled By: | Client |
| Date Tested: | 2/27/2025 | Tested By: | Sean Curry |

| GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE |
|---|
| Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11 |

| Lab Number | Sample Type | Sampling Location | Specification | |
|------------|---------------|-------------------|------------------|--|
| 25-0182 | Bankrun Shale | Stockpile | No Specification | |

| Sieve Size | | % | % | Spec. % |
|------------|--------|----------|---------|---------|
| mm | Inches | Retained | Passing | Pass |
| 100.0 mm | 4" | 0.0 | 100 | |
| 75.0 mm | 3" | 0.0 | 100 | |
| 63.0 mm | 2 1/2" | 0.0 | 100 | |
| 50.0 mm | 2" | 1.7 | 98 | |
| 37.5 mm | 1 1/2" | 5.1 | 93 | |
| 25.0 mm | 1" | 11.3 | 82 | |
| 19.0 mm | 3/4" | 6.2 | 76 | |
| 12.5 mm | 1/2" | 11.3 | 64 | |
| 6.3 mm | 1/4" | 17.4 | 47 | |
| 4.75 mm | #4 | 4.6 | 42 | |
| 2.00 mm | #10 | 11.7 | 31 | |
| 0.850 mm | #20 | 7.0 | 24 | |
| 0.600 mm | #30 | 1.7 | 22 | |
| 0.425 mm | #40 | 1.4 | 21 | |
| 0.150 mm | #100 | 4.0 | 17 | |
| 0.075 mm | #200 | 2.6 | 14 | |
| Pan | | 14.0 | | |

Comments:

Minus #200 by wash-sieve method.

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc. The results in this report relate only to the items inspected or tested.

PDF