**3348 Route 208, Campbell Hall, NY 10916**
**Phone: 845-496-1600 Fax: 845-496-1398**
12960 Commerce Lake Drive, A14, Fort Myers, FL 33913
42 Day Farm Road, West Stockbridge, MA 01266
1813 State Route 7, Harpursville, NY 13787
877 US-4, Schuylerville, NY 12871

| | | | |
|---|---|---|---|
| **Client:** | **Aden Aggregates** | **Project:** | 2023 Quality Control |
| **Item:** | 1 1/2" | **Project Number:** | 230081 |
| **Source:** | Grasso | **Lab Number:** | 24-0350B |
| **Date Sampled:** | 4/8/2024 | **Sampled By:** | Client |
| **Date Tested:** | 4/9/2024 | **Tested By:** | Sean Curry |

## GRADATION (SIEVE ANALYSIS) OF SOIL OR AGGREGATE

**Test Method(s): ASTM D422, C136, C117; AASHTO T88, T27, T11**

| Lab Number | Sample Type | Sampling Location | Specification |
|---|---|---|---|
| 24-0350B | 1 1/2" | Stockpile | No Specification |

| Sieve Size | | % | % | Spec. % |
|---|---|---|---|---|
| mm | Inches | Retained | Passing | Pass |
| 75.0 mm | 3" | 0.0 | 100 | |
| 50.0 mm | 2" | 26.7 | 73 | |
| 37.5 mm | 1 1/2" | 46.5 | 27 | |
| 25.0 mm | 1" | 21.1 | 6 | |
| 19.0 mm | 3/4" | 2.3 | 3 | |
| 12.5 mm | 1/2" | 0.5 | 3 | |
| 9.5 mm | 3/8" | 0.3 | 3 | |
| 4.75 mm | #4 | 0.5 | 2 | |
| Pan | | 2.1 | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Comments:

Emily J. Rodriguez

Report Reviewed By:

This report shall not be reproduced, except in full, without written permission from Advance Testing Company, Inc.
The results in this report relate only to the items inspected or tested.

PDF